

# Oil Field Environmental Incident Summary

**Incident:** 20140225172958

**Date/Time of Notice:** 02/25/2014 17:29

**Responsible Party:** MBI OIL & GAS, LLC

**Well Operator:** MBI OIL & GAS, LLC

**Well Name:** DAVIS/DVORAK 21-1 SWD

**Field Name:** CROOKED CREEK

**Well File #:** 8860

**Date Incident:** 2/25/2014

**Time Incident:** 04:30

**Facility ID Number:**

**County:** DUNN

**Twp:** 143

**Rng:** 97

**Sec:** 21

**Qtr:**

**Location Description:**

**Submitted By:** Darren Anderson

**Received By:**

**Contact Person:** Mike Reichert

PO BOX 7

BELFIELD, ND 58622-0007

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	600	Barrels	600	Barrels		
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

NA

**Areal Extent:**

**Potential Environmental Impacts:**

There were no impacts at this time. The spill was contained within the dike

**Action Taken or Planned:**

JTW and MBI vac trucks sucked up the standing water and a hot oil truck cleaned up the tanks

**Wastes Disposal Location:** 240 BBLS were put in a frac tank on site and the rest hauled to the Polinsky and Knudston SWDs

**Agencies Involved:****Updates**

---

**Date:** 2/26/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to on-location piping or valve leak, remained on location within the tank/treater diking, according to the report. NDIC retains oversight.